

TSB-OT-0014

Date: November 01, 2021

To: Internal, Sales, Distribution, and Sales Representatives

Subject: Ductless 17 Series, 18,000 BTU Heat Pump – Potential EEV Malfunction

In an effort of continuous product improvement and based on feedback from customers, Daikin recently discovered that a small number of Ductless 17 Series, 18,000 BTU heat pumps (Model Number: RXB18AXVJU) are experiencing inconsistent operation of the Electronic Expansion Valve (EEV) in certain climates, due to moisture, that can lead to oxidation. This condition is usually recognized by a failure to operate in cooling mode, along with error codes "UO" and "F3." The current resolution is to replace the EEV coil. In some cases, the PCB could also malfunction due to the EEV failure.

Procedure for Existing Field Installations


Repair is only needed for product not cooling and displaying "F3" and "U0" error codes. Daikin recommends using test procedure elaborated below to compare the resistance values of the EEV to the specifications. If the resistance values are outside specification, replace the EEV. If the PCB has malfunctioned due to the EEV failure, both will require replacement.

EEV Part Number: 2539348 PCB Part Number: 4022326

Orders for these parts can be placed with spare parts team through your normal parts ordering method or by emailing a purchase order to <u>SpareParts@daikincomfort.com</u>.

Test Procedure

Use the test procedure below or watch test procedure videos.




(Continued on next page)


Note: This Sales Bulletin constitutes "Confidential Information" as defined in, and is subject to the terms of, your Distributor Sales Agreement.

DAIKIN NORTH AMERICA LLC • 19001 Kermier Road • Waller, TX 77484 Main: 713.861.2500 • Marketing Fax: 713.331.3275 www.northamerica-daikin.com

Test Procedure (Continued)



Resistance values at the test points should read about 45 Ohms If the resistance value is open or too low (shorted) the coil has failed and will need to be replaced



(Continued on next page)


Note: This Sales Bulletin constitutes "Confidential Information" as defined in, and is subject to the terms of, your Distributor Sales Agreement.

DAIKIN NORTH AMERICA LLC • 19001 Kermier Road • Waller, TX 77484 Main: 713.861.2500 • Marketing Fax: 713.331.3275 www.northamerica-daikin.com



Future Inventory

The EEV coil design has been improved for 17 Series, 18,000 BTU heat pumps (Model Number: RXB18AXVJU). A new EEV design has already been implemented for all shipments starting August 1, 2021. There are no model number changes. Updated equipment can be identified by a green dot on the bar code label.



Reimbursement

Daikin will reimburse \$180 per unit for labor. Claims should be filed through Warranty Express with an Authorization type "Claim" and using Authorization Code 8718. All claims must be submitted by December 31, 2022. Please contact the Warranty Department at 1-855- DAIKIN1 if you need assistance with this process.

Please be patient as we assure that all product shipped from the Daikin Texas Technology Park has been updated. Please email John Pratt at <u>John.Pratt@daikincomfort.com</u> if you believe any of your customers have experienced this issue or have additional questions.

Note: This Sales Bulletin constitutes "Confidential Information" as defined in, and is subject to the terms of, your Distributor Sales Agreement.